

**In the Drawings:**

Permission is requested to substitute corrected Fig. 5 in place of original Fig. 5 which is corrected as follows:

(1) No. 402 has been corrected to 302

(2) "Client interface (500)" in the box has been corrected to 'Client interface';  
correct No. 502 has been entered outside the box.

(3) "Set-top box (502)" in the box has been corrected to 'Set-top box';  
correct No. 500 has been entered outside the box.

None of the above changes constitute new matter.



# REPLACEMENT SHEET




Fig.5



ANNOTATED MARKED-UP DRAWINGS




Fig.5